TEXAS RESEARCH INST INC AUSTIN INVESTIGATION OF SHIELDED AND UNSHIELDED CABLES.(U) NOV BO D GLOWE, S ARNETT NOO1 7967-15-DEG F/6 13/9 AD-A093 280 N00173-79-C-0129 NL UNCLASSIFIED 10-1 apa Charan 50





DISTRIBUTION STATEMENT A

Approved for public release;
Distribution Unlimited

8011 25 91



TEXAS RESEARCH INSTITUTE

TEXAS RESEARCH INSTITUTE, INC.



7967-15:DEG N00173-79-C-0129 11 November 1980

(14) 7967-12-DE,4

11) 11 Nov 1

9)

FINAL REPORT.

Investigation of Shielded and Unshielded Cables

/5) Contract N00173-79-C-0129



(P) 57 (

Submitted to:

Naval Research Laboratory Attention: Dr. Robert Timme P. O. Box 8337 755 Gatlin Avenue Orlando, Florida 32806

Submitted by:

D. E./Glowe S. L./Arnett
Texas Research Institute, Inc.
5902 West Bee Caves Road
Austin, Texas 78746

DISTRIBUTION STATEMENT A

Approved for public release; Distribution Unlimited

313430

TABLE OF CONTENTS

													Page
1.0	ABSTRACT			•		•		•	•		•	•	1
2.0	BACKGROUND		٠.	•		•		•			•	•	2
3.0	APPROACH		٠.	•		•		•		•	•	•	3
4.0	DISSCUSSION OF RESULTS .		• .	•		•		•			•	•	5
4.1 4.2 4.3 4.4 4.5 4.6	Mission Profile Strength Contribution of Crush Resistance Cable Puncture Resistance Hull Stuffing Tube Result Cost and Reliability	Shiel	ds	•	• •	•	• •	•		•	•	•	5 6 9 11 12 12
5.0	MISSION PROFILE		٠.	•		•		•		•	•	•	15
5.0	TEST PLAN			•		•		•		•			27
6.1 6.2	Cable Selection Test Selection	• •	• •	•	• •	•		•	• •	•	•	•	27 27
7.0	TEST RESULTS		• •	•		•		•		•	•	•	33
7.1 7.2 7.3 7.4 7.5	Tensile Properties Flexural Abrasion Bend Tensile Strength Crush Resistance Hull Stuffing Tube Perform Static Tension	 mance	• •	•	• •	•	• •	•		•	•	•	33 40 44 44 48 48
	LIST OF TABLES LIST OF FIGURES	• •	• •	•	•	DUJ	ces IIS IIC conn isti	TAB TAB oun fic	A&I ecd ati	on/			111
			1			•	AVA Los	٨٠	() () () () () () () () () ()	, a	ពល់វ	ur	

LIST OF FIGURES

		Page
F-1	FLOW CHART. PHASE 1, CABLE EVALUATION	4
F-2	ILLUSTRATION OF MIL-C-915/8 CABLE	29
F-3	ILLUSTRATION OF UNSHIELDED DSU-TYPE CABLE	30
F-4	ILLUSTRATION OF TRIDENT POLYETHYLENE CABLE	31
F-5	CABLE TENSILE TEST FIXTURE	35
F-6	TENSILE LOAD CHART - DSS-3 CABLE	38
F-7	TENSILE LOAD CHART - DSU-3	39
F-8	FLEXURAL ABRASION TESTER	41
F-9	FLEXURAL ABRASION TEST FIXTURE	42
F-10	CAPACITANCE CHANGE WITH TENSILE FORCE	47

TEXAS RESI	EARCH INSTITUTE, INC. LIST OF TABLES	
		Page
T-1	CABLE STRESS LIMITS	7
T-2	CABLE TENSILE PERFORMANCE	8
T-3	CABLE COMPONENT STRENGTH CONTRIBUTION	10
T-4	HULL STUFFING TUBE PERFORMANCE SUMMARY	14
T-5	MISSION PROFILE - TRANSPORTATION AND STORAGE CABLES	17
T-6	MISSION PROFILE - INSTALLATION AND MAINTENANCE, ENVIRONMENTAL CABLES	18
T-7	MISSION PROFILE - INSTALLATION AND MAINTENANCE, MECHANICAL DSS-2 CABLE	19
T-8	MISSION PROFILE - INSTALLATION AND MAINTENANCE, MECHANICAL DSS-3 CABLES	20
T-9	MISSION PROFILE - INSTALLATION AND MAINTENANCE, MECHANICAL DSS-4 CABLES	21
T-10	MISSION PROFILE - INSTALLATION AND MAINTENANCE, MECHANICAL FSS-2 CABLES	22
T-11	MISSION PROFILE - SSN SERVICE CABLES	23
T-12	MISSION PROFILE - SSBN SERVICE CABLES	24
T-13	MISSION PROFILE - SURFACE SERVICE CABLES	25
T-14	HYPOTHETICAL MAINTENANCE SCHEDULE	26
T-15	CABLE DESCRIPTION	28
T-16	CABLE TEST PLAN	32
T-17	TENSILE TEST PARAMETERS	34
T-18	CABLE COMPONENT TENSILE PROPERTIES	36
T-19	CABLE TENSILE - PROPERTIES	37
T-20	FLEXURAL ABRASION TEST SUMMARY	43
T-21	FLEXURAL ABRASION TEST OBSERVATIONS	45
T-22	TENSILE BEND TEST SUMMARY	46
T-23	CABLE CRUSH - TEST SUMMARY	49
T-24	STUFFING TUBE TEST SEQUENCE	50
T-25	CABLE ELONGATION IN STATIC TENSION	52

1.0 ABSTRACT

The mechanical properties of shielded and unshielded submarine cables (MIL-C-915/8E) were investigated to determine the effect of shielding on cable life, performance and reliability. Ten cables, five shielded and five unshielded, were selected for laboratory evaluation. A mission profile was developed to establish the mechanical stress limits cables must endure in service and a test sequence designed to measure tensile strength, flexural abrasion endurance, crush resistance, creep under static tension and performance in a hull stuffing tube.

The results of this program showed the following:

- 1. DSS-2 cable does not have adequate tensile strength and should have a strength member added. DSS-3 and larger cables have adequate tensile strength with and without the shield.
- Unshielded DSS-3 type cable does not perform satisfactorily in hull stuffing tubes.
- Shielding is not required to meet Mission Profile specifications for cable crush or flexural abrasion resistance.
- 4. Construction parameters other than shielding can significantly affect mechanical performance of cable.
- 5. Unshielded cable construction can result in increased reliability since it permits a thicker single jacket construction.
- 6. Unshielded cable construction can reduce the cost of cable by 8% to 20%.

2.0 BACKGROUND

This report covers the work performed on Phase I of Contract No. N00173-79-C-0129, "Investigation of the Strength of Shielded and Unshielded Cables."

This contract was awarded to Texas Research Institute, Inc. (TRI), in May, 1979, and was awarded as part of the FY79 Sonar Transducer Reliability Improvement Program (STRIP).

The STRIP Program investigates problems of current interest to the fleet. An objective of STRIP is to provide engineering solutions to problems that improve the life and reliability of sonar hardware. Underwater cables, an essential part of wet-end sonar hardware, have a history of failures which result in premature sonar replacement. Therefore, any improvement to cables lessening the frequency of failure would improve the reliability of the attached sonar hardware.

Puncture of the cable jacket is a known failure mode and has been identified in General Dynamics/Electric Boat Division Report No. U 443-78-036 as the most probable cause of cable failure. The jacket on shielded cables is relatively thin and can be easily punctured to the shield. A jacket puncture to the shield results in flooding of attached connectors, degradation of electrical properties and loss of the sonar transducer. As reasoned, constructing cable without the shield would provide a thicker, more puncture resistant cable less susceptible to premature failure.

The strength requirement of cable and the mechanical contribution of shielding to tensile strength, abrasion and crush resistance have been arguments for retaining shielded cable construction. Unshielded cables have had only limited use in the fleet, and data confirming unshielded cable mechanical performance have not been available.

3.0 APPROACH

The objective of this investigation was to provide quantitative data to compare the mechanical properties of shielded and unshielded cables, determine how these cables are used and what mechanical properties are required for use, identify failure modes for the cables under stress and provide an analysis of the cost and reliability tradeoff of shielded and unshielded cable.

To meet these objectives a three task laboratory program was designed as shown in Figure 1. The first task compiled background information on cables and resulted in a detailed Mission Profile description of cable exposures through all phases of cable life, procurement of samples of ten cable types for comparitive testing, and a test plan consisting of six mechanical tests. The second task exercised the test plan using the sample cables. Task 3 analyzed the resulting data and compared test values to service requirements.




Figure 1. Flow Chart - Phase I, Cable Evaluation

4.0 DISCUSSION OF RESULTS

Four specific questions have been addressed in this project and are:

- What forces do cables experience during installation, ship operations, and maintenance?
- 2. Does the shield provide additional tensile or crush strength and resistance to cable failure?
- 3. Does a shield provide any protection from puncture or does it contribute to failure by abrading and puncturing the insulation?
- 4. What is the cost and reliability tradeoff of shielded versus unshielded cables?

The following discussion addresses these questions and proposes solutions to identified problems.

4.1 Mission Profile

Two divisions of the Mission Profile identify mechanical stresses to cables.

The most strenuous exposure occurs during Installation and Maintenance and less strenuous, but longer term exposure occurs in Service.

Tensile stress occurs in both areas. Examination of installation and maintenance requirements shows that developed stress is dependent on cable type because of the difference in weight of the cables and the weights of an attached transducer. Independent of cable type is the possibility of a cable used as a hand hold by maintenance personnel and thereby supporting the full weight of a person, approximately 880 N. Although the DSS-3 Profile does show a maximum weight of 1960 N, when attached to TR-232 transducers, cable exposure to this value is unlikely since the conductors would break and detection would be obvious. Reports from the fleet have not been made of this excessive stress. More typical attached weight is approximately 240 N and hand hold occurence of 800 N is the most probable maximum tensile stress cables will see.

The state of the s

Long-term static tensile stress is a result of an unsecured vertically suspended length of cable. Shipboard cable installations are designed to be secured in cable trays and an unsupported cable run is not likely to occur. In the event an unsupported condition would exist, the resulting tensile load for 30 m of DSS-3 cable would be 70 N less than the overriding maintenance hand hold exposure.

Impact, crush and flexural abrasion and compression squeeze are the remaining mechanical cable stresses and occur during installation and maintenance.

Impact and crush values are identical between cable types, resulting from dropped tools, pinching in cable trays, foot traffic and similar abuse. Stress levels for impact and crush were extracted from Underwriter's Laboratory

Standard 44, and as this standard has been accepted by industry as describing practical endurance limits, are the levels recommended for cable specification. Flexural abrasion exposure and the accompanying flexural stress occurs during installation and the stated values are an approximation of maximum forces encountered due to cable installation in or over conduits. The reported exposures were determined by combining maximum tensile stress with a typical bend radius of 25 m.

Table 1 summarizes the maximum mechanical stresses as identified in the Mission Profile for cables during installation, ship operations, and maintenance.

4.2 Strength Contribution of Shields

The tensile results of whole cables shows that shielding contributes 15% to 18% of the strength of DSS-2 cable and 24% of the strength of DSS-3 cable. Comparing Butyl Size 3 cable to DSS-3 shows the shielding contributing 32% of overall strength. However, shielding does not increase the yield strength of cables.

Table 2 lists the required and measured strengths of the test cables. Both shielded and unshielded Size 2 cables do not meet the strength requirements for

· --- 「新子子の一年」を大学の大学の大学にはあっている。

TABLE 1
CABLE STRESS LIMITS

EXPOSURE		CABLE	TYPE	·
	DSS-2	 DSS-3 	DS S-4	 FSS-2
Tensile N	880	1960*	880	880
Crush N/50 mm	5290 	5290	52 9 0	5290
Impact N•m	2	2	2	2
Flexural Abrasion Load (N) Over 50 mm Mandrel	255 	1960 *	490 	862

^{*}Load for TR-232 system only.

TABLE 2
CABLE TENSILE PERFORMANCE

Cable	Tensile	e (N)	Yield (N)
	M.P. ¹	Test	 Test
DS S-2	880	620	390
DSU-2	880	500	390
DSS-3	1960 ²	1120	660
DSU-3	1960 ²	860	640
Buty1-3	880	760	550
DSS-4	880	1540	1040
FSS-2	880	1320	 840
TRIDENT	880	800	620

^{1:} M.P. = Mission Profile requirements.

^{2:} Stress Requirement for TR-232 only; other systems require 880 N. $\,$

the 880 N hand hold maintenance requirements and would break under this load. The DSS-3 exceeds the 880 N requirement and the DSU-3 is within 20 N of meeting this load. The 880 N hand hold requirement is a high estimate of the weight of maintenance personnel and average exposure would likely be less than this value. Both DSS-3 and DSU-3 can, therefore, be expected to survive the exposure.

Full loading by heavy transducers, 1960 N for DSS-3 although possible, is not likely to occur. Use of cables as a handle to lift transducers does frequently occur but the lifted units generally weight less than 240 N. Cables used as a hand hold during maintenance with the resulting 880 N load is likely to occur and should be considered in cable design and as a valid exposure limit.

Table 3 itemizes the strength contribution of the cable components. In all cables the conductors were a major strength component. However, for the TRIDENT cable the polyethylene insulation contributed 29% of the cable strength which exceeds the 25% strength contribution of shielding for DSS-3 and FSS-2 cables. Also, the Butyl cables showed 9% strength contributed by the insulation materials. DSU-3 cable, a similar construction to that of the Butyl cable, has 17% strength contributed by the belt and jacket.

It is concluded that shielding can act as a strength member and for small diameter cable such as DSS-2, a strength member is required. However, shielding alone does not provide sufficient strength for Size 2 cable and improved strength members should be considered. For DSS-3 and larger cables, shielding or other strength member is not required to prevent cable breakage. Insulation materials can add to tensile endurance as exhibited by the TRIDENT polyethylene cable and lessen endurance as in the Butyl Size 3 cable.

4.3 Crush Resistance

The obtained data for cable crush characteristics shows that shielded cables DSS-2 and DSS-3 are 7%-15% more resistant to crush failure than a DSU

TABLE 3
CABLE COMPONENT STRENGTH CONTRIBUTION

Cable	Stren	ngth Contributio	n (%)
Type	Insulated	Belt and	
	Conductors	Jacket	Shield
DSS-2	89	11	none
Unshielded	09	11	l
	ļ		İ
DSS-2	67	16	17
 DSU-2	88	12	l none
DSU-2 	00	12	l
DSS-3	61	15	24
Double Jacket	!		
DSS-3	62 I	13	25
Single Jacket	02	15	i - 23
1		_	1
DSU-3	83	17	none
DS S-4	77	5	18
		_	İ
FSS-2	68	7	25
Butyl	91	9	non e
Size 3	71		l
			ļ
TRIDENT	71	29	none
Polyethylene			<u> </u>

type cable. However, all measured cables with the exception of the DSS-2 Special Unshielded, and the Unshielded Butyl Size 3 survived crushing forces in excess of the mission profile limit of 5300 N/50 mm length. The unshielded TRIDENT polyethylene cable was approximately four times more resistant to crush than the elastomeric shielded cables and ultimately failed with an open circuit rather than by shorted conductors. This again indicates that properties of the cable insulating materials can add to or detract from the crush resistance of cables more than shielding.

It is concluded that shielding is not required for protection from crush damage. Also, increased crush resistance can be obtained, if required, by selecting tougher materials for insulation such as that used for the TRIDENT polyethylene cables.

4.4 Cable Puncture Resistance

Cable puncture was not found to be a result of conductor wire or shield wire breakage. The flexural abrasion test did fatigue shield and conductor wires to failure but electrical measurements made during the test did not show degradation of insulation resistance or shorting to ground or between conductors. The failure mode identified during the crush test was conductor—to—conductor shorting. Jacket or primary insulation puncture by the shield was not found to be a failure mode.

Puncture of the cable by external forces was not investigated in this program. Shielding can be expected to inhibit cable puncture to the conductors by external forces; however, once the jacket is punctured to the shield, water ingression along the shield will occur and the cable will fail at the connector.

It is concluded that shielding does not contribute to internal puncture related failures and can only delay and not prevent failure from external puncture.

4.5 Hull Stuffing Tube Results

As shown in Table 4, three of the four samples of unshielded cable (DSU-3) moved over 6 mm during the pressure cycling, and all four of them continued moving at each cycle. The shielded cables moved less than 2 1/2 mm in the test series, and appeared to become set after two pressure cycles and thereafter move little or none.

4.6 Cost and Peliability

Complete cost data for unshielded cables is not available from manufacturers since DSU cable is not routinely made. Removing the shield results in a considerable manufacturing time savings in cable assembly and could also delete the requirement for double jacket. Estimates of the cost savings by shield removal of 8% to 20% have been made by cable manufacturers.

Impact of shield removal on the reliability of cable varies with failure mode and cable size. The most likely failure mode identified in the GD/EB report was puncture of the cable jacket. Since internal puncture was not found in the test program, puncture from external causes is the mechanism of concern. Shield removal would provide as much as 150% thicker elastomer puncture barrier in DSS-3 cable than is presently available. The probability of external puncture to unshielded conductors would be less than the probability of puncture through the jacket only. Shield removal would appear therefore to increase cable reliability.

Considering the small size 2 cables, shield removal would increase the probability of failure due to tensile stress. Size 3 cables are not as affected in a tensile failure mode and the reliability impact of shield removal would not be significant.

The TRIDENT cable demonstrated superior performance in tests of flexural abrasion and crush, and typical performance in the other areas tested. It

therefore appears to be a highly reliable cable; the reliability of cable assemblies using this material is most likely to depend on the reliability of the terminations.

TABLE 4
HULL STUFFING TUBE PERFORMANCE SUMMARY

CONDUCTORS MOVEMENT IR (mm) Ohr Good 1.78 >20	OVEMENT (mm) (mm) (1.78 1.18 1.14	8 8	CONDUCTORS MOVEMENT (mm) Cood 2.41	ACCUMUL. MOVEMENT IR (mm) Ohms 2.41 >20G	1 R 0 hms >20G	CONDUCTORS MOVEMENT (mm) Good 2.41	ACCUMUL. MOVEMENT (mm) 2.41
poog		200	Good	2.41	>200	Good	2.41
poog							1.40
-		 ì	Cood	1.40 >16	>1G	Good	
Poop	1.45	- >30c	Good	1.85	 >30c	Good	16.1
Poog		1000 j		1	1	1	1
9j poog		100G		!			ł
Good 1		100c	Good	3.56	>100C	Good	3.81
Good 1		100C	Good	17.14	>100C	Poog	18.03
		22.48 6.68 1.78		22.48 >100G 6.68 >100G 1.78 >100G 1.47 >100G	22.48 >100c 6.68 >100c 1.78 >100c Good 1	22.48 >100c 6.68 >100c 1.78 >100c Good 1	22.48 >100G 6.68 >100G 1.78 >100G Good 3.56 >100G 1.47 >100G Good 17.14 >100G

5.0 MISSION PROFILE

A mission profile is a description of environmental and mechanical stresses to which hardware is exposed during the lifetime of that hardware. Environmental stresses include temperature extremes, thermal shock, moisture exposure, U.V. radiation, pressure excursions and other exposures that contribute to materials degradation or change in properties. Mechanical stresses address physical changes in materials caused by tensile, torsional or compressive loading, fatigue, abrasion and other similar factors.

The information developed in a mission profile is essential input to product design and to verification test design. The maximum and minimum stress exposure called out in a mission profile are used as guidelines to design and to test products for endurance to expected use. As such the mission profile is a tool for insuring product reliability and life expectancy.

For this program, the mission profile for cables was developed to provide maximum and minimum stress limits for comparison of cable types. Three categories of mission profile were established, Transportation and Storage (Table 5), Installation and Maintenance: Environmental (Table 6) and Mechanical (Table 7 through 10); and Service: SSN (Table 11), SSBN (Table 12) and Surface Ship (Table 13).

The general format used for describing the mission profile is as follows:

- Column 1 Exposure number for identification.
- Column 2 Exposure description.
- Column 3 Range of exposure, maximum and minimum values that can be experienced. This range covers all ship use.
- Column 4 Where the exposure occurs during use.
- Column 5 Time weighted description of extreme exposure reduced to one year's estimated stress, based on maximum or minimum exposure values.

- Column 6 Time equivalent of extreme exposure.
- Column 7 Time weighted description of a typical or average exposure reduced to one year's estimated stress.
- Column 8 Time equivalent of typical exposure.
- Column 9 Companion exposure that may contribute synergistically to materials changes in service.

Information contained in the mission profile was collected from various sources. Among these are product specifications, steaming data or estimates of this data, consensus opinion of Naval personnel associated with maintenance and fleet operation, published literature and manufacturers' opinions. In some instances hard numerical data for an exposure were not available and the data presented were therefore estimated.

Of the profile categories, Transportation and Storage exposures apply to all cable types. Installation and Maintenance was subdivided into environmental exposures, which apply to all cables, and mechanical exposures, which apply only to specific cable sizes. The subdivision was required because of the difference in weight and use between cables. Service profiles were also subdivided into SSN, SSBN and Surface Ship exposures because of the different mission requirements between these ship types. Maintenance schedules are different for these ship types as shown in Table 14, and influences the inservice exposure levels hardware will see.

MISSION PROFILE - TRANSPORTATION AND STORAGE CABLES TABLE 5:

	Γ	-										_			_ 					-	_		 	-				_	_ 		_			-
	COMPALION	EXPOSURES			Humidity	Ultraviolet	Air Pollution					Humidity	Temperature	Air Pollution			Temperature	Ultraviolet	Air Pollution					Temperature	Humidity	Air Pollution				Temperature	Humidity	1440 hrs Ultraviolet		
	PER	1 YR.		_				_	8640 hrs	_				8640 hrs			_		_		8640 hrs					2880 hrs						1440 hrs		
ycles)	CONTINUING	LONG TERM							-6° to +38°C					100 kPa			;				+10 to 32°C	Dew Point				770 uw/cm ²	8 hrs/day x	360 days					8 hrs/day for 180 days	
ime or (PER	1 YR.	 006	hrs	_		360	hrs			16	hrs			7 20	hrs		2880	hrs			_	410	hrs			- - -		24	hrs				1 se-
DURATION (Time or Cycles)		EXTREME	70°C for	5 hrs/day x	180 days	_30°c	12 hrs/day x	30 days			12 kPa	2 flights x	8 hrs		-30°C	Dew Point	30 days	-38¢+	Dew Point	120 days			2625 µW/cm ²	1.5 hrs/day	270 days				500 ps1	8 hrs/day	for 3 days ^D			Per MIL-
		OCCURANCE	Storage	Outside					Covered	Storage	Air	Transporta-	tion	Storage	Storage			_					Storage	Outside	Uncovered		-		Storage			-		Transporta-
	EXPOSURE	RANGE	-30° to	+70°C		_					to 100	kPa	`		-30° to	+38°C Dew	Point						0-2625 лм/	сш ² (д 290-	400 mm				0-500 ps1a		-			Per MIL-
		EXPOSURE	Temperature	in air			_				Pressure in	Air			Hum1d1ty								Ultraviolet	Radiation					Air	Pollution				Rough
		8	-			7			m		4			2	9		ı	_		•	œ		σ			01			=		,	12		13

a - psi - Pollution Standard Index per Fed. Reg. Vol. 44 #219
 b - Based on Los Angeles Experience, 1975.
 Ozone is major contaminant.
 c - Rough handling as defined by specification due to lack of service data.

TABLE 6 MISSION PROFILE - INSTALLATION AND MAINTENANCE, ENVIRONMENTAL CABLES

				D	TRATION	(Time or Cycle	es)	<u> </u>
NO	EXPOSURE	EXPOSURE RANGE	OCCURANCE	 EXTREME	PER 1	CONTINUING LONG TERM	PER 1 YR.	COMPANION EXPOSURES
	Temperature in Air	 -30° to +60°C 	Dry Dock ^C Winter	 -30°C for 30 Days	 720 Hrs] 	j	 Humidity Air Pollution
2	<u> </u>] — — — — — — — — — — — — — — — — — — —	-11°to +11°C for 180 Days		
3	<u> </u>	! !	Dry Dock ^c Summer	+60°C for 8 Hrs/Day	720	!		! !
4	! ! !]] 		90 Days	Hrs 	 +11°to +39°C for 180 Days		1
	Temperature in Water	-2° to +32°C	Dockside Winter	-2°C for 90 Davs	2160 Hrs	!		
6	} !	 		1	1	-1° to +15°C for 180 Day		
7 8	! ! !	[Dockside Summer	+32°C for	2160 Hrs	 		
	Thermal	ΔT<50°C	Dry Dock ^c	 ΔT = 50°C	<u></u>	for 180 Day	4320 Hrs	Humidity
	Cycling	MS30 C	Dry Dock	1 Cycle/Day 90 Days		; ; ;		Air Pollution
10	 					ΔT = 30°C 1 Cycle/Day for 180 Days	180 Cvcle	
11	Humidity	-30° to +38°C Dew	Dry Dock ^c Dockside	-30°C Dew Point	720 Hrs		.00 07020	Temperature Air Pollution
12	<u> </u> 	Point		30 Days +38° Dew Point	2880 Hrs] [
13	!] 		120 Days	 	 +10°to +32°C Dew Point	8640 Hrs	
14	Air Pollution	0 -500 psi ^a	Dockside and Dry Dock ^c	500 psi 8 hrs/day for 3 daysb	24 Hrs			Temperature Humidity
15				l		200 ± 50 psi 8 hrs/day for 180 days	ļ	

a - psi - Pollution Standard Index per Fed. Reg. Vol. 44 #219
 b - Based on Los Angeles experience, 1975. Ozone is the major contaminant.
 c - Drydock frequency varies with ship type.

TABLE 7
MISSION PROFILE - INSTALLATION AND MAINTENANCE, MECHANICAL DSS-2 CABLE

					URATION (T	DURATION (Time or Cycles)	
		EXPOSURE			PER 1	CONTINUAL	PER 1
0 <u>2</u>	EXPOSURES LOAD	RANGE	OCCURANCE	EXTREME	YR.	LONG TERM	YR.
-	Tensile Load, Dynamic	<u><250 N a</u>	Installation	250 N	l Cycle		
8		q N 088>	Maintenance	880 N	1 Cycle		
ŧΩ						240 N	l min.
4	Impact	<2 N•m	Maintenance Installation	2 N·m	1 Cycle ^c		
'n	5 Crush	5300 N/50mm Length	Maintenance Installation	5300 N/50mm 1 Cycle ^d Length	l Cycle ^d		
و	 Internal Abrasion	250 N Tension on 50mm dia.	Installation	250 N on 50mm dia.	5 Cycles		
		mandrel		mandrel			

a - Weight of maximum cable length plus maximum attached transducer weight b - Hand hold support.
c - Specified in Underwriter Lab STD 44 (Par 82).
d - Specified in Underwriter Lab STD 44 (Par 81).

MISSION PROFILE - INSTALLATION AND MAINTENANCE, MECHANICAL DSS-3 CABLES TABLE 8

					DURATION	DURATION (Time or Cycles)	
S S	NO EXPOSURE LOAD	EXPO SURE RANGE	OCCURANCE	EXTREME	PER 1 YR.	CONTINUAL LONG TERM	PER 1 YR.
	Tensile Load, Dynamic	<2000 N B	Installation	2000 N	1 Cycle		
		q N 088	Maintenance	880 N	1 Cycle		
						240 N	l min.
4	Impact	< 2 N·B	Maintenance Installation	2 N•B	l Cycle ^c		
2	Crush	5300 N/50mm Length	Maintenance Installation		1 Cycled		
9	Internal Abrasion	2000 N Tension 50mm dia. mandrel	Installation	2000 N on 50mm dia. mandrel	5 Cycle		

a - Weight of maximum cable length plus maximum attached transducer weight.
b - Hand hold support.
c - Specified in Underwriters Lab STD 44 (Par. 82).
d - Specified in Underwriters Lab STD 44 (Par. 81).

TABLE 9
MISSION PROFILE - INSTALLATION AND MAINTENANCE, MECHANICAL DSS-4 CABLES

					DURATION	DURATION (Time or Cycles)	
0N	EXPOSURE LOAD	EXPOSURE RANGE	OCCURANCE	EXTREME	PER 1 YR	CONTINUAL LONG TERM	PER 1 YR
	Tensile Load, Dynamic	<u><490 N a</u>	Installation	N 067	l Cycle		
- 5		√880 N b	Maintenance	N 088	1 Cycle		
<u>ო</u>						240 N	1 Min.
4	Impact		Maintenance Installation	2 N•m	l Cycle ^c		
ν <u> </u>	Crush	5300 N/50mm Length	Maintenance Installation		1 Cycled		
9	Internal Abrasion	490 N Tension on 50mm dia. mandrel	Installation	490 N on 50mm dia. mandrel	5 Cycles		

- Weight of maximum cable length plus maximum attached transducer weight. a - Weight of Manager.
b - Hand hold support.
c - Specified in Underwriters Lab STD 44 (Par.82).
d - Specified in Underwriters Lab STD 44 (Par.81).

. IABLE 10
MISSION PROFILE - INSTALLATION AND MAINTENANCE, MECHANICAL FSS-2 CABLES

				D	URATION (T	DURATION (Time or Cycles)	
NO	EXPOSURE LOAD	EXPOSURE RANGE	OCCURANCE	EXTREME	PER 1 YR.	CONTINUAL LONG TERM	PER 1 YR.
-	Tensile Load, Dynamic	∠860 N a	Installation	N 098	1 Cycle		
2		√880 N b	Maintenance	N 088	l Cycle		
6						240 N	l min.
4	Impact	≤ 2 N·m	Maintenance Installation	2N•ш	1 Cycle ^C		
2	Crush	5300 N/50mm Leng.h	 Maintenance Installation 	 5300 N/50mm 1 Cycle ^d Length 	1 Cycle ^d		
ا و	Internal Abrasion	860 N Tension on 50mm dia. mandrel	Installation	860 N on 50mm dia.	5 Cycles		

Weight of maximum cable length plus maximum attached transducer weight
Hand hold support
Specified in Underwriters Lab STD 44 (Par 82).
Specified in Underwriters Lab STD 44 (Par 81).

e o b

TABLE 11 MISSION PROFILE - SSN SERVICE CABLES

	1	I DANCE CT		1	Ţ	RE (hrs or cycle	1	COMPANY
NO.	EXPOSURE	RANGE OF	OCCURANCE	EXTREME	PER 1	CONTINUING	PER 1	COMPANION EXPOSURE
1	Temperature in Air	-55° to	Dockside	+60°C, 1.5	405 h	r		Humidity Air Pollu-
2	1			-30°C 12 hr/ day - 30 days	360 h	r i		tion
3	į	į	į	1	 	+3° to +37°C for 270 days	6480 hr	j
4	i 1	i !	Arctic Sur-	-55°C for 21 days	504 h		1	i !
5	 Temperature In Sea Water	1 -2° to 1 +32°C	Tropical Ser.	 +32°C for 90 days	2160 h		1	Pressure Vibration
6	 	1	Artic Service	-2°C for 90 days	2160 hi	 	 	i violacion i
7_	<u> </u>	<u> </u>	<u> </u>		İ	-1° to 11°C for 90 days	2160 hr	i !
8	Thermal	ΔT ≤ 50°C	Dockside	ΔT = 50°C	270		1	Humidity
9	Cycling 				cycles	ΔT ≤ 30°C	365 cycles	Air Pollution
	 Thermal Shock	∆T ≤ 53°C	 Diving-Tropic	ΔT <u><</u> 28°C	 30 cycles	 	 	
11 	 	<u> </u> 	Diving-Arctic	ΔT <u><</u> 53°C	3 cycles	1	1	<u> </u>
2	 Pressure 	 100 to 4100 kPa		 4100 kPa day = 90 days	 180 hr 	 		 Temperatur Vibration
13	 	 	 			700 to 2100 kPa for 90 days	2160 hrs	
	Pressure Cycling	100 <p<4100 kPa</p<4100 		100 to 4100kPa 2/day - 90days				
.5		! 	! !		 	700 to 2100kPa 90days	180 cycles	
6	Humidity	-55° to +38°C Dev		38°C D.P. 24 hr/day -	 6480 hr			Temperature Air
7		[1	 	 	110° to 32°C D.P 270days	16480 hrs	
	Air Pollution	 0-500 psi [#] 	i l	500 psi 8 hrs/day for 3 days ^c	24 hr	 	, ; ! ; ! ;	Temperature Humidity
9 9 			_				1440 hra	
0	Vibration	Per MIL- STD-167-1 ^b	At Sea	Per MIL-STD - 167-1				Temperature Pressure
	Explosive Shock	Per CIPS ^b			l series			Pressure
, †	Tag-41-	N-22 4	1				01/6	Humidity
. !	Tensile Load, Static		All Service	 			8640 hrs	Temperature Vibration Air
i			<u> </u>				i	Pollution

of the book of the second water to the second of the

NOTPS: a psi - Pollution Standard Index per Ped. Reg. Vol. 44 #219
b Vibration and explosive shock as defined by specification due
to lack of service data.
c Based on Los Angeles experience, 1975. Ozone is the major contaminant.
d Static stress based on 10 meters of unsupported cable. DSS-2 = 59 N,
DSS-3 = 98 N, DSS-4 = 120 N, FSS-2 = 120 N.

TABLE 12 MISSION PROFILE - SSBN SERVICE CABLES

	T			DURATION OF	EXPOSU	E (hre or cycle	es)	1
NO.	EXPOSURE	RANGE OF EXPOSURE	OCCURANCE	EXTREME	PER 1 YR.	CONTINUING LONG TERM	PER 1	COMPANION EXPOSURE
1	Temperature Air	-55° to +60°C	Dockside	+60°C, 1.5 hr/day-40days -30°C 12 hr/	60 hrs		 	 Humidity Pollution
2	1	1	1	-30°C 12 hr/ day - 20 days	240 hrs			Air Pollution
3	į	į	į		† <u>.</u>	+3° to 37°C	1440	
4]		Arctic Sur-	-55°C for 21 days	504 hrs	for 60 days	hr	!
5	 Temperature Sea Water	-2° to +32°C	Tropical Service	 +32°C for 270 days	6480 hrs	-1° to 11°C		Pressure
6	! !		Artic Service	-2°C for 270 days	6480 hrs	 	1	
7	 				 	11°C 11°C for 270 days	6480 hr	
8 9	 Thermal Cycling 	åτ <u><</u> 50°C	Dockside 	ΔT - 50°C	60 cycles	 ΔT ≤ 30°C	60	 Humidity Air Pollution
	<u> </u> 		 		 	<u> </u>	cycles	
	Thermal shock	ΔT ≤ 53°C	Diving-Tropic	-	300 cycles		<u>i</u>	
11	! <u>}</u>	<u> </u>	Diving-Arctic	<u>ΔT< 53°C</u>	300 cycles	<u> </u>	 	
12	Pressure	 100 to 4100 kPa		 4100 kPa day - 300 days	 7200 hrs	 		Temperatur Vibration
13	! 	<u> </u>	! !			700 to 2100kPa for 300 days	7200 hrs	
	 Pressure Cycling 	100 <p<4100 kPa</p<4100 		 100 to 4100kPa 2/day-300days		 		•
15		<u>i</u> 1	i !			 700 to 2100kPa	600 cycles	
16	Humidity	-55° to +38°C Dew Point	į į	 38°C D.P. 24 hr/day - 60 days	 1440 hr	[] [Temperature Air Pollution
17 		1	j 1 †	l days		+10° to +32°C D.P 60days		1011011011
18 	Air Pollution	0-500 pmi [®]	!!!	500 psi 8 hrs/day for 3 days ^c	 24 hr			Temperature Humidity
19		 	 	act a days	1	200 + 50 psi 8 hrs/day for 60 days	48 hr hr	
20	Vibration	Per MIL- ISTD-167-1b		Per MIL-STD - 167-1	l series		i i	Temperature Pressure
	Explosive Shock	 Per CIPS ^b 			 1 series			Pressure
- !	Tensile Load, Static	Note d	All Service		ļ	Continuous Load per Note d	8640 hr	Humidity Temperature Vibration Air Pollution

NOTES: a psi - Pollution Standard Index per Fed. Reg. Vol. 44, #219 b Vibration and explosive shock as defined by specification due to lack of service data.

c Based on Los Angeles experience, 1975. Ozone is the major contaminant.
d Static stress based on 10 meters of unsupported cable. DSS-2 = 59 N, DSS-3 = 98 N, DSS-4 = 120 N, FSS-2 = 120 N.

TABLE 13

MISSION PROFILE - SURFACE SERVICE CABLES

		 -	-r	DURATION O	F EXPOSUR	E (hrs or cycle	·s)	Ţ	
NO.	. EXPOSURE	RANCE OF EXPOSURE	OCCURANCE	EXTREME	PER 1	CONTINUING LONG TERM	PER 1	COMPANION EXPOSURE	
1	Temperature in Air	0° to +38°C	 Dockside 	0° C 180 days	 4320 hr	 	 	Humidity Pollution	
2]	1	! 	+38°C	 8640 hr	1	l I		
3	1	1	1		Ţ	+3° to +37°C for 360 days	8640 hr		
4	Temperature In Sea Water	1-2° to 32°C	Artic	-2° C for 180 days	4320 hr				
5			 Tropical 	 +32°C for 360 days	 8640 hr	 	 	Pressure Vibration	
6	1	<u> </u>		T		0° to +30°C for 360 days	8640 hr		
7	Pressure	1100 to 250	 Service 	250 kPa day 360 days	8640 hr			Temperature Vibration	
8	 	 	 		<u> </u>	100 to 250 kPa for 360 days	8640 hrs	 	
9	 Humidity 	0° to +38°C Dew Point	 Service 	38°C D.P.	8640 hr		 	Temperature Pollution	
10	į	1	j	<u> </u>	 	10° to +32°C D.P 360days	8640	į	
	Air Pollution	0-500 psi ^a	Dockside	500 psi, 8 hrs/day for 3 days	24 hr			Temperature Humidity	
12	 				İ	200 + 50 psi 360 days	18640 hr		
13	 Vibration 	 Per MIL- STD-167-1 ^b	At Sea	 Per MIL-STD - 167-1	1 series			Temperature Pressure	
	 Explosive Shock	Per CIPS ^b	At Sea	Per CIPS	l series			Pressure	
	Tensile Load, Static	Note d	All Service	 	j j	Continuous Load per Note d	8640 hr	Humidity	

NOTES: a psi - Pollution Standard Index per Fed. Reg. Vol. 44 #219
b Vibration and explosive shock as defined by specification due
to lack of service dats.
c Based on Los Angeles experience, 1975. Ozone is the major contaminant.
d Static stress based on 10 meters of unsupported cable. DSS-2 = 6 Rg,
DSS-3 = 10 Kg, DSS-4 = 12 Kg, FSS-2 = 12 Kg.

TABLE 14
HYPOTHETICAL MAINTENANCE SCHEDULE

_	DRYDOCK - RES	STRICTED AVAILABILITY	DRYDOCK	- OVERHAUL
SHIP TYPE	 INTERVAL	TIME IN DRYDOCK	 INTERVAL 	TIME IN DRYDOCK
SSN	 22 - 24 Months	45 Days	 5 1/2 - 7 Years	6 - 10 Months
SSBN	22 - 24 Months 	45 Days	 5 1/2 ~ 7 Years	6 - 10 Months
SURFACE	 		 3 - 4 Years 	28 - 45 Days
 			 	·

6.0 TEST PLAN

6.1 Cable Selection

Ten cable designs were selected for evaluation, five shielded and five unshielded, and were examined, dissected and the internal components measured.

A list of the cables and physical description of each is given in Table 15.

Cables were selected according to their current or proposed use in the fleet. Shielded cables include DSS-2, DSS-3 (single and double jacket), DSS-4 and FSS-2 made to MIL-C-915. The unshielded cables include TRIDENT specification polyethylene cable, DSU-2 and DSU-3 made to a proposed specification, and unshielded DSS-2 and butyl cable made to in-house descriptions. Figures 2-4 are illustrations of the cable samples.

6.2 Test Selection

Since the mechnical attributes of shielded and unshielded cable were of primary interest in this program, the Mission Profiles were reviewed for data indicating mechanical stress to the cable. The Installation and Maintenance profiles showed that tensile strength, crush and flexure resistance, and static stress creep were mechanical stresses influencing cable performance. Cables, DSS-3 in particular, are used in hull stuffing tubes and must perform satisfactorily in this service.

Standard tests were reviewed for those applicable to cable performance.

The sources reviewed included American Society for Testing and Materials (ASTM),

Underwriter Laboratory, military and federal specifications and other industrial

sources. Table 16 lists the tests selected for this program, the measurements

to be made, and the test objectives.

Carried States Line

TABLE 15 CABLE DESCRIPTION

													-	
			-	JACIC						COND	CONDUCTORS		-	
CABLE	TIFE	(kg/km)	CABLE DIA.	(cable Dia. THICKNESS (cas) (mm)	LAYERS	(E)	THICKNESS (mm)	(E)	NO.	INSULATION	THICKNESS (mm)	COLOR	STRAND DIA.	COMMENTS
DSS-2 Special	unshielded	<u>.</u>	6.89	[2,16-3,68			1	12.79	7	Single Rubber	0.63	399	14.0	Conductors loose in belt, will slide under tension.
058-2	shlelded	·;	91.0	-11.52	~	6.72	0.76-1.65	12.79	~ ~ ~ ~ ~ ~ ~	Single Rubber	0.63	798	14.0	Double jacket separates easily, shield is tightly adherred to inner jacket. Conductors separate easily.
DSU-2	unshielded	3.5	6.6	1.90-4.19	2	<u> </u>	1	12.54	~ ~	Rubber w/ plastic sheath	0.63	35 80	0.38	Double jacket separates easily, jacket separates from belt easily, conductors loose in belt.
DSS-3 Double Jacket	shielded	7.2	12.70	2.16	~	8.25	0.63-3.30	3.56	~~~~~ ~	Single Rubber	66.0	7.78	0.51	Double jacket separates essily, shield removed essily, conduc- tors separate essily,
DSS-3 Single Jacket	shielded	7.2	12.70	12.16	-	8.25	0.89-3.43	13.81	~ ~ ~ ~ ~	Single Rubber	0.89-1.14	798	0.51	Jacket tightly adherred to belt, conductors loose in belt.
DSU-3	unshielded	4.	12.70	12.41	-	8	1,78-3,43	3.03	7	Single Rubber	0.76	798	0.46	Jacket tightly adherred to belt, conductors loose in belt.
DSS-4	shielded	* **	12.70	1.78	8	8.25	0.76-3.68	 18.		Rubber w/ plastic sheath	16.0	798	19.0	Double jacket separates easily, shield separates easily, con- ductors separate easily.
FSS-2	shielded	* *	12.70	12.29	~	8.25	0.89-3.43	2.54	*	Single Rubber	0.63	3	17.0	Double jacket separaten easily, shield separates easily, corr- ductors adherred to belt.
BUTYL	unshielded		12.70	2.29	-	8.25	0.63-1.90	18.	~	Single Rubber	0.63-1.27	39	15.0	Jacket separates from belt easily, conductors longe in belt.
TRIDENT Polyethylene	unehlelded		7.11	1.65-3.05	-		1	06.1	~ ~ ~ ~	Double Plantic	0.28	Clear over 1 85W	0.30	Jacket hard and tight over conductors.
•														

and alternate over a construction

FIGURE 2
ILLUSTRATION OF MIL-C-915/8 CABLE

	DIA.)	A			- C -	
		 Outer	 Inner		1	ı Primary	Conductor of
		Jacket	Jacket	Shield	Belt	Insul.	7 Strand Tinned
							Copper Strand
	Dia.(mm)	Mat '1.	Mat'l.	Mat'l.	Mat'1.	Mat'l.	Dia. (mm)
DSS-2/E	10.16	Neoprene	Synthetic Rubber	Tinned Copper	Synth. Rubber	Synth. Rubber	0.41
DSS-3/A	12.70	Neoprene	None		Synth. Rubber	Synth. Rubber	0.51
DSS-3/E	12.70	Neoprene	Synthetic Rubber		Synth. Rubber	•	0.51
DSS-4/E	12.70	Neoprene	Synthetic Rubber		Synth. Rubber	Synth. Rubber	0.61
FSS-2/E	12.70	Neoprene	Synthetic Rubber		Synth. Rubber	Synth. Rubber	0.41

FIGURE 3
ILLUSTRATION OF UNSHIELDED DSU-TYPE CABLE




FIGURE 4 ILLUSTRATION OF TRIDENT POLYETHYLENE CABLE




TABLE 16 CABLE TEST PLAN

TEST	PROCEDURE	MISSION PROFILE REFERENCE	TEST	MEASUREMENTS, OBSERVATIONS	OBJECTIVE
Tensile Breaking Strength	ASTM-D-412 ASTM-D-470	Installation 6 Maintenance	Cable & Components, All Samples	Ultimate Strength, Elongation, Order of Component Break, Electrical Continuity	Ultimate Strength, Resistance to Maintenance and Installation Abuse
Flexural Abrasion	DuPont Design	Installation & Maintenance	Cables, All Samples	Stress, Cycles, Elongation, Continuity Resistance Breakdown (Megohm) Electrical Insulation	Fatigue Endurance, Insulation Degrada- tion Due to Internal Conductor or Shield Break
Breaking Bend Strength		Installation & Maintenance	Cables, All Samples	Ultimate Strength, Elongation, Mode of Electrical Failure (Open or Short)	Mode of Electrical Failure Ultimate Strength Due to Tension over a Radius
Crush Resistance	ANSI/UL STD.44-1977	Installation & Maintenance	Cables, All Samples	Force to Failure Mode of Electrical Failure (Open or Short)	Resistance to Crushing Force, Mode of Failure
Performance Hull Stuffing Tube		Service	Cables, (DSS-3, DSU-3)	Electrical Characteristics Physical Dimensions, Grommet Compression, Leakage, Cable Movement Permanent Set in Cables	Movement, Leakage, Electrical characteristics in stuffing tube
Creep in Static		Installation & Maintenance,	Cables, All Samples	Stress, Time, Elongation Electrical Characteristics	Fallure due to creep

7.0 TESTS RESULTS

7.1 Tensile Properties

The tensile properties of the complete cables and of the cable components were measured following the testing parameters shown in Table 17. All complete cables, cables less jacket and cables less jacket and shield were fixtured on a 102 mm diameter capstan grip for testing as shown in Figure 5. The individual components removed from the cable were cut into dogbone tensile specimens using ASTM-D-412 Die C. Wedge grips were used to hold elastomer samples and to hold the cut elastomer and conductor samples for tensile testing.

Tensile results for the cable components are shown in Table 18. Maximum force applied to each sample and the sample elongation at maximum force is reported and in all cable samples, maximum force was obtained at the point of first conductor break. Stress for the elastomer dogbone samples was calculated on the basis of cross sectional area of the sample. The jacket on the unshielded DSS-2 and on the DSU-2 did not separate from the belt, and therefore, a cable strength less jacket was not measured. Also, the TRIDENT polyethylene cable does not have a separate jacket and, therefore, jacket data are not reported.

Cable tensile properties are given in Table 19. Three samples of each cable type were tested and for all cables, the maximum force was obtained when a conductor broke. The elongation at maximum force is also reported. The yield strength was calculated for each cable and is included in the data. Figure 6 shows a recorded force-elongation plot for DSS-3 cable and and Figure 7 the recorded data for DSU-3 cable. These curves were typical of those obtained for other cable sizes.

TABLE 17
TENSILE TEST PARAMETERS

Test No.	Test Description	Sample	Strain Rate (mm/min)	Gage Length (mm)
1	Tensile strength, cable, 102 mm díameter Capstan grips	Cable and components, 1.83m sample	51	102
2	Tensile strength, wire, wedge grips		51	51
3	Tensile strength, insulation, wedge grips	Elastomer insulation cut to ASTM- D-412, Die C	51	51

I

September of Committee of the Committee



FIGURE 5 Cable Tensile Test Fixture

TABLE 18 - CABLE COMPONENT TENSILE PROPERTIES

CABLE TYPE	COMPLET	COMPLETE CABLE	LESS JACKET	ACKET	LESS JACKET SHIELD	ACKET ILD	CONI W/INSU	CONDUCTOR W/INSULATION	STRENGTH	ENT TH MPa
	Max		Max		Max		Max			
	Force	Elong.	Force	Elong.	Force	Force Elong.	Force	Force Elong.		
	2	9	z	9	z	9	z	%	Jacket	Belt
DSS-2	220	77	 			 	730			
100000000000000000000000000000000000000	2	}					067		0.11	1
DSS-2	620	9/	570	47	097	99	210	7	0.6	5.9
DSU-2	200	20					210		13.1	0.9
DSS-3 Double Jacket	1140	70	066	8 4	710	94	340	19	e. 80	6.1
DSS-3 Single Jacket	1130	77	1010	89	720	38	340	19	0.6	6.7
DSU-3	098	95	089	30			370	16	12.4	16.5
DSS-4	1540	84	1490	99	1200	54	290	16	7.6	8.3
FSS-2	1320	57	1230	51	006	36	230	15	6.3	0.6
BUTYL Size 3	092	73	730	99			340	13	11.0	10.3
TRIDENT Polyethylene	008	67					280	12		
	_									

Carrier of the group of the time of the

TABLE 19 CABLE TENSILE - PROPERTIES

		Maximum	Maximum Force (N)	(Z		YIELD STRENGTH (N)
SAMPLE TYPE	1	2	3	AVERAGE	ELONGATION	1% OFFSET
DSS-2 Unshielded	510	510	530	520	297	700
DSS-2	919	650	550	009	76%	390
DSU-2	520	067	900	200	20%	390
DSS-3 Double Jacket	1130	1110	1170	1130	202	099
DSS-3 Single Jacket	1130	1130	1110	1120	77%	099
DSU-3	860	840	870	1860	298	940
DSS-4	1540	1570	1570	1550	84%	1040
FSS-2	1320	1330	1310	1320	57%	840
BUTYL Size 3	750	740	790	760	73%	550
TRIDENT Polyethylene	870	770	750	800	267	620




FIGURE 6
TENSILE LOAD CHART
DSS-3 CABLE

The state of the s




FIGURE 7
TENSILE LOAD CHART
DSU-3 CABLE

7.2 Flexural Abrasion

A flexural abrasion test was designed to fatigue the metal components of the cables while under stress. The objective of this test was to induce failure of the shield wires and measure any penetration of the jacket or primary insulation by broken wires through monitoring electrical continuity of the wires to ground.

The apparatus used for this test was based on a design developed by DuPont for evaluating internal abrasion of Kevlar electro-mechanical cables. The test and fixture were presented by DuPont at the February, 1979 Marine Technology Society Cables and Connectors workshop in San Diego, and no formal specification is known to exist. The equipment is schematically shown in Figure 8 and consists of a 50.8 mm diameter octagonal mandrel submerged in a water bath, a drive system to move test cables over the mandrel and a tensioning system to stress the cables while in motion. Figure 9 shows cables attached to the apparatus.

In operation, the cables were individually tensioned using dead weights, bent 180° around the octagonal bar and oscillated at 30 cycles/minute with a 127 mm stroke length. The continuity of the conductors was monitored during the test. Insulation resistance between the conductors and shielding and between the conductors, shield and water was also monitored to detect possible penetration of the insulation by broken wires. Failure was defined as shield or conductor discontinuity or a short indicating penetration of the insulation.

Table 20 shows the results of the test. The number of cycles at failure is noted along with the increase in cable length. The failure mode in each failed cable was an open conductor. Shorts to ground or degradation of insulation resistance was not found, indicating that insulation was not punctured by broken wires. Two cable samples, FSS-2 and TRIDENT Polyethylene did not fail and were




FIGURE 8

FLEXURAL ABRASION TESTER



FIGURE 9
Flexural Abrasion Test Fixture

TABLE 20 FLEXURAL ABRASION TEST SUMMARY

Sample Number	Type	Cable Stress (kPa)	Cycles to Failure	Elongation at Failure (%)	Failure Mode
 1 	DSS-2 Unshielded	600	 1900 	2.8	Open Conductor
! 2 	DSS-2	470	13000 	2.8	 Open Conductor
3	DSU-2	490	10000	1.4	Open Conductor
4	DSS-3 Double Jacket	440	15000	2.1	Open Conductor
5	DSS-3 Single Jacket	440	11000	1.4	Open Conductor
6	วรบ-3	440	8800	0.7	Open Conductor
7	DSS-4	440	11000	1.4	Open Conductor
8	FSS-2	440	>20000	1.4	No Failure
9	BUTYL Size 3	440	6700	3.5	Open In
10	TRIDENT Polyethylene	570	>20000	<0.7	 No Failure

removed from the test after 20,000 cycles. All test cables were dissected at the conclusion of the test to confirm failure modes and the observations made are summarized in Table 21.

7.3 Bend Tensile Strength

Samples of DSS-3 and DSU-3 cable were tested in tension around a 51 mm diameter mandrel to determine the effect of compressive force in conjunction with a tensile force on cable failure characteristics. The ends of the sample were fixtured to a 102 mm diameter capstan grip with the center supported by the mandrel. The samples were tensioned at a rate of 51 mm/minute while the continuity of the conductors and the resistance between conductors and shield was monitored. Applied force was continuously recorded during the test.

Three samples of both cable types were tested and test results are summarized in Table 22. The location of conductor failure was between the mandrel and the grip, and no damage was observed in the cables in contact with the mandrel.

A separate sample of DSU-3 was tested in the same fixture and mutual capacitance of the conductors monitored. Capacitance as a function of applied force is plotted in Figure 10.

7.4 Crush Resistance

The resistance of cable to crush was measured following the test procedures outlined in ANSI/UL Standard 44-1977, PAR 81. This test requires that a cable sample be placed between two 51 mm wide parallel steel plates and a force applied to plates at a rate of 13 mm per minute. The compressive force was continuously recorded and electrical continuity between conductors and steel plates monitored.

TABLE 21
FLEXURAL ABRASION TEST OBSERVATIONS

Sample Number	Type	Observation
1	DSS-2 Unshielded	Both conductors separated.
 2 	DS S-2	Shield intact, both conductors separated.
 3 	DSU-2	Both conductors separated.
4	DSS-3 Double Jacket	Shield separated 50%, no shield penetration of insulation. Both conductors separated.
5	DSS-3 Single Jacket	Shield intact, both conductors separated.
6	DSU-3	Both conductors separated.
7	DSS-4	Shield intact, both conductors separated.
8	FSS-2	Cable intact, no conductor or shield breakage.
9	BUTYL Size 3	Both conductors separated.
10	TRIDENT Polyethylene	Cable exterior roughened, no internal damage observed.


TABLE 22
TENSILE BEND TEST SUMMARY

 - CABLE TYPE	AVERAGE FORCE TO FAILURE (N)	FORCE PER CABLE (N)	FAILURE ANALYSIS
DSS-3 Double Jacket	2222	1111	Conductor broken be- tween mandrel and grip, no damage ob- served over mandrel, 40-50% shield broken, separation of lst and 2nd jacket observed.
DSU-3	17 1 3 	857	Conductor broken be- tween mandrel and grip, no damage ob- served over mandrel, separation of jacket and belt observed.

Ann market and

andrew Art with the State of th

FIGURE 10



CAPACITANCE CHANGE with Tensile Force

CABLE TYPE - DSU-3
TOTAL LENGTH - 1.5 m
Two Lengths in Tension Around a 50 mm Dia. Mandrel

Test results are given in Table 23 and dissection of samples after testing confirmed the indicated failure modes. In no instance did a conductor or shield short to the compression plates before the conductors shorted to each other. In case of TRIDENT polyethylene cable, the conductors parted and did not short.

7.5 Hull Stuffing Tube Performance

The performance of DSS-3 and DSU-3 cables was evaluated in a hull stuffing tube made to NAVSEA DWG. No. 900-56202-F-1197101 (Stuffing Tube PP for SS and TSP type cable). This assembly is a compression grommet seal device used as a cable feed-through in ship hulls. The test cables were assembled in the stuffing tube according to NAVSEA procedures and subjected to three series of hydrostatic pressure sequences as shown in Table 24. Criteria for evaluation was measurement of cable movement during or between test sequences, water leakage through the stuffing tube and electrical characteristics of the conductors and shield.

Three samples of DSS-3 and four samples of DSU-3 cable were tested. Table 4 summarizes the results through the three complete test sequences. Insulation resistance of the conductors and shield was measured at the end of each complete sequence as was cable movement through the fitting. Sample Numbers 4 and 5 of DSU-3 cable were removed after the first test sequence because they shipped too far in the stuffing tube during the first pressure test sequence. None of the cables showed electrical failure. All cable samples were dissected at the conclusion of the test. The shielded cables showed permanent deformation of the shield and partial shield breakage. Defects or permanent set were not observed in the non-shielded cables.

7.6 Static Tension

All cable samples were subjected to a static tensile load simulating conditions that might exist when a vertical length of cable is hung unsecured. The

TABLE 23 CABLE CRUSH - TEST SUMMARY

CABLE	CABLE DIAMETER	COMPRESSION	% COMPRES-	071	AD TO F	LOAD TO FAILURE (N)	2	FAILURE
TYPE	(mm)	AT FAILURE (mm)	SION		2	3	AVG	MODE
DSS-2 Unshielded	8 8 8 8	4.1	20	1660	2260	2660	2200	Conductor-conductor short
DSS-2	10.16	5.2	51	0909	0209	5250	57.90	Conductor-conductor short
DSU-2	9.91	5.6	26	74440	5340	5340	5040	Conductor-conductor short
DSS-3 Double Jacket	12.70	6.9	54	6110	7110	7110	6770	Conductor-conductor short
DSS-3 Single Jacket	12.70	6.9	55	6220	0299	0299	 6520 	Conductor-conductor short
DSU-3	12.70	6.9	54	6220	0.299	5340	0 209	Conductor-conductor short
DSS-4	12.70	6.7	53	6330	5550	2440	57.80	Conductor-conductor short
FSS-2	12.70	7.5	59	9780	8890	11110	9930	Conductor-conductor short
BUTYL Size 3	12.70	5.4	73	1770	1770	1770	1770	Conductor-conductor short
TRIDENT Polyethylene	7.11	5.7	78	26600 25400	25400	28900	27 000	Open conductor
								İ

TABLE 24
STUFFING TUBE TEST SEQUENCE

Cycle	Operation
 1	Pressurize 0-1.82 MPa - repeat for 20 cycles
 2	Pressurize 0-3.55 MPa - repeat for 20 cycles
3	Pressurize 0-6.99 MPa - repeat for 20 cycles
1 4 	Pressurize 0-10.44 MPa - repeat for 20 cycles
) 5	Pressurize 0-13.89 MPa - repeat for 20 cycles
 6 	Pressurize 0-1.82 MPa - hold at 1.72 MPa for 8 hrs.
7	Reduce pressure to 0.1 MPa - hold at 0.1 MPa for 8 hrs.

load used for this test was the same as the load used for flexural abrasion testing. A sample length was 305 mm and was monitored for elongation during the test. The test was terminated after 30 days and the test results are shown in Table 25.

TABLE 25
CABLE ELONGATION IN STATIC TENSION

SAMPLE NO.	CABLE	LOAD (kPa)	TIME	ELONGATION % *
1	DSS-2 Unshielded	607	30 Days 3 Days	<1.0
2	DSS-2	469	30 Days	<1.0
3	DSU-2	489	30 Days	<1.0
4	DSS-3 Double Jacket	441	30 Days 3 Days	<1.0
5	DSS-3 Single Jacket	441	30 Days 3 Days	<1.0
6	DSU-3	441	30 Days	<1.0
7	DSS-4	441	30 Days	<1.0
8	FSS-2	441	30 Days	<1.0
9	BUTYL Size 3	441	30 Days 30 Days	<1.0
10	TRIDENT Polyethylene	565	30 Days 	<1.0

^{*}All samples elongated 3.17 mm per 305 mm gage length.